

MIPP TPC Status

- All bad sticks have been repaired (90% of bad channels)
- Stand/rail installation completed
- TPC moved into clean room
- Taken apart and inspected
- Still working on leaky connectors
- TPC holds voltage under N₂!
- Gating grid --> next slide

Who will help make the ... TPC Gating Grid

